



SOLID WOOD POST STABILITY

Treated wet *Pinus radiata* timber products may experience certain movements, such as twisting and shrinkage, as they dry out. It is crucial to ensure proper seasoning or drying of the timber before application to mitigate these potential issues. Failure to do so may result in structural instability or aesthetic discrepancies in your project.

It is also essential to be aware of the phenomenon known as 'checking' during the drying process. Checking refers to the formation of cracks on the surface of the wood as it dries and will be particularly severe in direct sunlight.

Checks in *Pinus radiata* are a normal occurrence and are not considered a structural defect.